

	VOLLRATH NO.	DESCRIPTION	SHEET NO.
1	XMIX101840	TOP COVER BLUE, 7/10QT	4
2	XMIX1006	MOTOR ASM 110-120V, 7/10QT	4
2	XMIX0016	MOTOR ASSEMBLY 220V 7&10 QT	4
3	XMIX1002	CONTROL PANEL, 7/10QT	5
4	XMIX0005	PWR CTRL BOX 110-120V, 7/10QT	5
4	XMIX0006	PWR CTRL BOX 220-230V, 7/10QT	5
5	XMIX1027	RING GEAR, 7/10QT	4
6	XMIX1024	AGT SHAFT TAPERED PIN, 7/10QT	4
7	XMIX1084	BOWL LIFT SUPP BRACKET, 7/10QT	5
8	XMIX1008	BOWL LIFT ELBOW, 7/10QT	5
9	XMIX1007	BOWL LIFT HANDLE, 7/10QT	5
10	XMIX0702	MIXING BOWL SS, 7QT	3
11	XMIX0703	FLAT BEATER, 7QT	3
12	XMIX0704	DOUGH HOOK, 7QT	3
13	XMIX0705	WIRE WHISK, 7QT	3
14	XMIX1025	BEARING TRANS SHAFT, 7/10QT	4
15	XMIX1022	MOTOR O-RING, 7/10QT	4
16	XMIX1023	MOTOR OIL SEAL, 7/10QT	4

	VOLLRATH NO.	DESCRIPTION	SHEET NO.
17	XAA0012	CABLE RESTRAINT (FMA,SKA,FFA)	5
18	XAA0005	POWERCORD 120V (NEMA5-15P)	5
19	XMIX1058	BASE TRIM, 7/10QT	5
20	XMIX1004	CONTROL PANEL STICKER, 7/10QT	5
21	XMIX1082	SEAT OF MICRO SWITCH	4
22	XMIX1013	MICROSWITCH BL/SHFT, 7/10/40QT	5
23	XMIX1020	CARBON BRUSH, 7/10QT	4
24	XMIX1021	CARBON BRUSH CAP, 7/10QT	4
25	XMIX1083	WIRE HARNESS CP/PC BOX, 7/10QT	5
A	XMIX1015	TRANSMISSION SHAFT ASM, 7/10QT	4
B	XMIX1016	WORM GEAR SHAFT ASM, 7/10QT	4
C	XMIX1006	MOTOR ASM 110-120V, 7/10QT	4
D	XMIX1014	PLANETARY HEAD ASM, 7/10QT	4
E	XMIX1008	BOWL LIFT ELBOW, 7/10QT	5
F	XMIX1026	BOWL SUPPORT ARM ASM, 10QT	5
G	XMIX1031	BOWL GUARD ASM, 7/10QT	3
-	XMIX0001	GEARBOX GREASE, 7-40QT	NOT SHOWN
-	XMIX0002	PLANETARY GREASE, 7-40QT	NOT SHOWN





