




2 WELL HOT & COLD 120V WIRING DIAGRAM

IMPORTANT – PLEASE OBSERVE VIEWER ORIENTATION NOTE IN EACH BOX

ITEM NUMBERS
FC-6HC-02120
FC-6HC-02120-AD



- PS - POWER SUPPLY
- HPS - HIGH PRESSURE SWITCH
- PT - PRESSURE TRANSDUCER
- COMP - COMPRESSOR
- OLP - OVERLOAD PROTECTION
- MF - MOTOR FAN
- CS - STARTING CAPACITOR

